









The printer status relay and trigger signal were used with the previous Videojet 100 Excel printer. In the Oak/1616, they were not yet connected to the new Videojet 1520 printer.



+24VDC and 24V COM are sourced from TVD module, and supplied through the Oak board. 5V COM is sourced from PS1, and is also supplied through the Oak board.

PART: American GFM Ultrasonic Cutter with Centroid M400		
DRAWN BY: Marc Leonard	REV: 1	DATE: 10-Jan-2018
SCALE: none	SHEET: 4 OF 4	FILE: K102837_4.VCD